

Date: Tuesday, 26/09/2006 3:13:10 PM
 User: Linda Lacelle

Process Sheet

Customer : CC-DAR01 Dart Aerospace Ltd.	Drawing Name : D3337-041
Job Number : 28736	
Estimate Number : 10804	
P.O. Number : <i>N/A</i>	Part Number : D3337041
This Issue : 26/09/2006 S.O. No. : <i>N/A</i>	Drawing Number : HAI
Prsht Rev. : NC	Project Number : <i>N/A</i>
First Issue : <i>N/A</i> Type : OVERHEAD	Drawing Revision : <i>N/A</i>
Previous Run : 00015	Material : <i>N/A</i>
Written By : _____	Due Date : 27/09/2006 Qty: 3 Um: Each
Checked & Approved By : _____	
Comment : _____	

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
1.0	SMALL FAB 1	SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1
 REMOVE BAGS FROM HAI LANDING GEAR
 D3337-041 B21849

u 26-09-26 (3)

2.0	QC5	INSPECT WORK TO CURRENT STEP
-----	-----	------------------------------



Comment: INSPECT

26-09-26 (3)

3.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1
 ID & STK WITH NEW B/N

u

4.0	QC21	FINAL INSPECTION/W/O RELEASE
-----	------	------------------------------



Comment: FINAL INSPECTION/W/O RELEASE

(3) 26-09-26

Job Completion



u 26-09-26

50

DART AEROSPACE LTD		Work Order:	21849
Description: Float Cover LH		Part Number:	D3337-041
Dwg: D3337 Rev A		Qty:	9
		Page 1 of 1	

Step	Location	Procedure	By	Date	Qty
1	DC	Issue Traveler	HA	04.11.04	9
2	PG	Issue P/O: <u>2007077</u> Float Cover LH as per Dwg D3337 Possible Supplier: Tulmar Material release note & Process sheet is required	u	04-11-04	9
3	RG	Receive and Inspect for transit damage Enure material release note & Process sheet are attached	CL	05/01/05	9
4	QC5	Inspect assembly 100%	CL	05/01/05	9
5	ST	Identify and Stock in Kwik Float cell	CL	05/01/06	9
6	AC	Cost / part: <u>115.92</u>	Sur	05-01-07	9
7	DC	Close W/O <u>115.92</u> Inspect Level 21	HA	05.01.12	9

Rev	Date	Change	Revised By	Approved
A	04.11.04	New issue	KJ/JLM	

RELEASED
04/04/11.07

REFERENCE ONLY